

EARTHQUAKE FELT ACROSS CDEMA PARTICIPATING STATES

SITUATION REPORT No. 2

AS OF 1:00PM ON AUGUST 24, 2018

UPDATE: Magnitude 6.9 Earthquake at 5:31 PM (21/08/18) Magnitude 6.0 Aftershock at 9:28 AM (22/08/18)

Summary of Damage Assessments

The following is a report from the Office of Disaster Preparedness and Management (ODPM) Trinidad and Tobago on the ongoing damage assessments following the earthquake and aftershocks between August 21 and 22, 2018.

The National Emergency Management Operations Center (NEOC) was activated on August 21, 2018 at 7:00 PM (AST). The Tobago Emergency Management Agency (TEMA) reported no significant damage to critical infrastructure. The EOC at TEMA was deactivated on August 22, 2018.

The NEOC at the ODPM continues to undertake Initial Damage Assessments (IDA) and Damage and Needs Assessments (DANA). Following the completion of the IDA and DANA, a Damage and Loss Assessment will be conducted. Please find attached full report from the ODPM.

Map Illustrating Initial Damage Assessment in Trinidad Post the 6.8 EQ. (21-08-2018)



65 Government Offices being assessed
22 assessments completed



20 Schools are being assessed












Assessments completed in Arima, Sangre Grande & Mayaro/Rio Claro
Assessments ongoing in 11 Corporations
80% Assessments completed in Tobago



Power Outages – The Trinidad and Tobago Electricity Commission is working to restore electricity in affected areas

Legend

-  Fire Station
-  Police Station
-  POS General Hospital
- No. of Houses Damaged/ Regional Corporation
-  0.0 - 0.0
-  0.0 - 1.0
-  1.0 - 3.0
-  3.0 - 5.0
-  5.0 - 8.0



The CDEMA CU remains in regular contact with the National Disaster Coordinator at the ODPM and will continue to provide updates as necessary. For more information on earthquake safety please visit www.weready.org